

Homecheck Environmental



Contamination Risk PASSED

Professional Opinion

Argyll Environmental Consultants have passed this report in accordance with the definition of contaminated land within Part 2A of the Environmental Protection Act 1990. Please refer to the Professional Opinion page and Section 1 for further information.



Flood Risk: None Identified

Refer to Section 2 for further information

Conveyancer Guidance

While this report may have identified areas at risk of flooding within 250m of the search centre, we consider there to be no significant risk of flooding to the property. Please refer to Section 2 for further information.



Radon: IDENTIFIED

Refer to Section 3 for further information



Ground Stability: IDENTIFIED

Refer to Section 4 for further information

Other Influential Factors:

Refer to Section 5 for further information

Environmental Constraints: IDENTIFIED

See Section 5a

Report issued for the property at The Bank Coombes Moor Coombes Moor Presteigne LD8 2HY

Report Reference **311649245_1_1**

National Grid Reference 336260 263010

Customer Reference REH/643543/2 Wilding/3460111_HCP

Report Date **22 May 2023**

Contact Details

If you require assistance please contact your Search Provider or phone Customer Services on 0844 844 9966 or email helpdesk@homecheck.co.uk

Landmark Contribution

By purchasing this report, the recipient may be eligible for Remediation Contribution of up to £100,000 if served with a Remediation Notice by the Local Authority. Such a notice may require the homeowner to pay for all, or contribute to, the remediation of the property. For more information see Landmark's Terms and Conditions.





Homecheck Environmental



Professional Opinion Contamination Risk **PASSED**

In the professional opinion of Argyll Environmental Consultants, the level of contamination risk associated with the information disclosed in the Homecheck Professional report dated 22nd May 2023 and reference 311649245_1_1, REH/643543/2 Wilding/3460111_HCP for

The Bank Coombes Moor Coombes Moor Presteigne LD8 2HY

1) is unlikely that the property would be designated "contaminated land" within the meaning of Part 2A of the Environmental Protection Act 1990.

2) is unlikely to have an adverse effect on the security of the property for normal lending purposes.

The professional opinion refers to Section 1 of this report and should always be read in conjunction with the full text of that report. No physical site inspection or survey has been carried out or is proposed.

Approved by

Argyll Environmental Ltd



Contents and Summary of Findings



Site Location



Section 1: Contamination Risk Findings

Contamination Risk	0-25m	25-250m	250-500m	See Section
Designated Contaminated Land	No	No	No	1a
Landfill and Waste	No	No	No	1b
Potentially Contaminative Activities	No	Yes	No	1c
Known Pollution Incidents	No	No	No	1d
Other Potential Contaminative Land Uses	No	Yes	n/a	1e



Section 2: Flood Findings

Flood	0-25m	25-250m	See Section
River Flooding	No	Yes	2a
Coastal Flooding	No	No	2b
Surface Water Flooding	No	Yes	2c

Section 3: Radon Findings

Radon	Result	See Section
Radon Affected Property	Yes	3

Section 4: Ground Stability Findings

Ground Stability	Result	See Section
Man-Made Factors	No	4a
Natural Factors	Yes	4b



Section 5: Other Influential Factors

Other Influential Factors	Result	See Section
Environmental Constraints	Yes	5a



i Aerial Photograph


The photograph below shows the location of the site to which this report relates.



Presteigne, LD8 2HY



The map below shows the location of the site to which this report relates.




Presteigne, LD8 2HY

Section 1: **Contamination Risk Findings**

The whole of section 1 deals with potential sources of contamination and provides the information by which this report has either been passed or referred for assessment.

Section 1a and 1b: Information Map

The map detailed below shows the location of the Designated Contaminated Land and Landfill and Waste features highlighted within sections 1a and 1b of this report.



Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 4 of 21

Report Reference 311649245_1_1

Section 1a: Designated Contaminated Land

The data within this section tells you whether your property or surrounding area has been identified by the Local Authority as "Contaminated Land" under the Environmental Protection Act 1990. Should there be an indication of contamination, it is not necessarily a cause for concern. Your report will be assessed by our professional environmental consultants who will advise you what, if any, considerations need to be made should you proceed with the property purchase.

Enquiry			Result
Has any contaminated I	No		
Map ID Reference	Location	Details	Distance Contact
Contaminated Land Re	egister Entries and Notice	S	
No factors identified	for this property		

Section 1b: Landfill and Waste

The information in this section is telling you about active and historic landfill and waste sites within 500 metres of the property. Having a landfill or waste site near your property does not necessarily mean that you or the property will be affected. However, it is something you need to be aware of, because landfill and waste can have a detrimental effect on the surrounding environment, house value and health. A closed landfill/waste site should be given equal consideration to an active site, because of landfill byproducts. For instance, landfill with lots of organic material can continue to produce odours and gas for many years.

Enquiry			Result
Have any landfill and v	vaste sites been identified	l within 500m of the property?	Νο
Map ID Reference	Location	Details	Distance Contact
Registered Landfill Sit	es		
No factors identified	l for this property		
BGS Recorded Landfil	l Sites		
No factors identified	for this property		
Local Authority Recor	ded Landfill Sites		
No factors identified			
Local Authority Recor	ded Landfill Coverage		
The following list de	tails the Local Authorities that co	over the search area who have made landfill data availab	ole:
Herefordshire Cou	ncil	- Has not been able to supply Land	fill data 4
For further informat contacts indicated a	5 5 ,	ocal Authority Recorded Landfill data you may wish to fo	orward enquiries to one or more of the
Historical Landfill Site	S		
No factors identified	d for this property		
Permitted Waste Sites	- Authorised Landfill Sit	te Boundaries	
No factors identified	for this property		
Environmental Permit	tting Regulations - Waste	e	
No factors identified			
Integrated Pollution (
	Control Registered Waste	e Sites	

Homecheck® Report

Report Reference 311649245_1_1


©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 5 of 21

Map ID Reference	Location	Details	Distance Contact
Registered Waste Treat	ment or Disposal Sites		
No factors identified f	or this property		
Registered Waste Trans	fer Sites		
No factors identified f	or this property		

Report Reference 311649245_1_1 ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 6 of 21

i Section 1c and 1d: Information Map

The map detailed below shows the location of the Potentially Contaminative Activities and Known Pollution Incidents features highlighted within sections 1c and 1d of this report.



Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY

Report Reference 311649245_1_1 ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 7 of 21

Section 1c: Potentially Contaminative Activities

This section describes current and historic licensed activities within 500 metres of the property, which have the potential to cause contamination or have an impact on the environment. The licensed activities could range from pollution to air, land or water; storage or disposal of radioactive substances; or storage of hazardous or explosive materials. Licences may no longer be active, but the nature of the past activity means it could still have an impact.

Enquir	у			Result	
Have	Yes				
Map ID	Reference	Location	Details	Distance	Contact
Local	Authority Pollution Pre	evention and Controls			
	No factors identified for this p	property			
Local	Authority Integrated P	ollution Prevention And Co	ntrol		
	No factors identified for this p	property			
Integr	ated Pollution Control	S			
g.	No factors identified for this p				
Enviro	nmontal Darmitting D	aulations Industry			
Enviro	onmental Permitting Re	• •			
	No factors identified for this p	broperty			
Conse	nt to Discharge to Con	trolled Waters			
1	Name: Mr Carl Searles	Proposed Dwelling At Coombes	Type: Sewage Discharge	159m	1
	Reference: Eprsb3293wc	Moor Coombes Moor Presteign Herefordshire Ld8 2hy	Discharge Type: Sewage Discharges - Final/ Treated Effluent - Not Water Company		
			Property Type: DOMESTIC PROPERTY (SINGLE) (INCL FARM HOUSE)		
			Discharge Environment Type: Freshwater Stream/River		
			Receiving Water: Tributary Of River Lugg		
			Status: New issued under EPR 2010		
			Date of Issue: 19th October 2020		
			Positional Accuracy: Located by supplier to within 10m		
Radioa	active Substances Regi	ster			
	No factors identified for this p				

Planning Hazardous Substance Consents

No factors identified for this property

Control of Major Accident Hazards Sites (COMAH)

No factors identified for this property

Notification of Installations Handling Hazardous Substances (NIHHS)

No factors identified for this property

Explosive Sites

No factors identified for this property

Next Steps

If you would like any further information in respect of the above findings we recommend that you contact the relevant Local Authority or the Environment Agency/Natural Resources Wales, their contact details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.

Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY

Report Reference 311649245_1_1

©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 8 of 21


Section 1d: Known Pollution Incidents

The data within this section describes unpermitted activity in your area (e.g. polluting incidents, or exceedance of permitted allowance) where the activity led to a prosecution or enforcement of regulations. Whilst all of these records are historic, the nature of the incident may have long term effects.

nquiry			Result	
lave any known pollution incidents been identified within 500m of the property?			No	
ap ID Reference	Location	Details	Distance	Contact
cal Authority Pollutic	on Prevention and Contr	ol Enforcements		
No factors identified for	or this property			
nforcement and Prohi	bition Notices			
No factors identified for	or this property			
	or this property bstance Enforcements			
	bstance Enforcements			
anning Hazardous Su No factors identified fo	bstance Enforcements			
lanning Hazardous Su No factors identified fo	bstance Enforcements or this property o Authorised Processes			
lanning Hazardous Sul No factors identified for rosecutions Relating to	bstance Enforcements or this property o Authorised Processes or this property			

i Section 1e: Information Map

The map detailed below shows the location of the Other Potential Contaminative Land Uses features highlighted within section 1e of this report.



Section 1e: Other Potential Contaminative Land Uses

This section describes either current or historic activity, which could be considered to be contaminative. This section makes no statement about whether the activity requires a licence; however our environmental experts deem that the activities described in this section could lead to potential contamination. The information is taken from a variety of sources including trade directories, Landmark's extensive historical map collection and analysis of historic activity. Records are highlighted due to the potential for contamination to exist.

Enqu	uiry			Result	
Hav	e any other potentia	l sources of contamination l	been identified within 250m of the property?	Yes	
Мар	ID Reference	Location	Details	Distance	Contact
uel	Station Entries				
	No factors identified for	or this property			
Iont	temporary Trade Di	irectory Entries			
	No factors identified for				
orn	ner Marshes				
	No factors identified for	or this property			
Pote	ntially Infilled Land	l (Non-Water)			
2	Not Supplied	Not Supplied	Unknown Filled Ground (Pit, quarry etc)	250m	-
			Map Published Date: 1983		
ote	ntially Infilled Land	l (Water)			
	No factors identified for	or this property			
Pote	entially Contaminat	ive Industrial Uses (Past La	and Use)		
3	Not Supplied	Not Supplied	Class: Quarrying of sand & clay, operation of sand & gravel pits	250m	-
			Map Published Date: 1890 - 1904		
Histo	orical Tanks And En	ergy Facilities			
	No factors identified for				

Next Steps

If you would like any further information in respect of the above findings we recommend that you contact our Customer Services Team, whose details can be found in the 'Useful Contacts' section of this report. Further Information is also available in the 'Useful Information' section.

Coombes Moor


Coombes Moor Presteigne, LD8 2HY



The whole of this section deals with potential sources of flooding that may impact the property.

Section 2a and 2b: River and Coastal Flood Map

The map detailed below shows the location of potential river and coastal flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.




Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 12 of 21

Report Reference 311649245_1_1

1 Section 2c: Surface Water Flood Map

The map detailed below shows the location of potential surface water flood risk. The potential risk has been modelled on the basis of an event occurring on average every 75, 200 or 1000 years.





Report Reference 311649245_1_1 ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 13 of 21

Section 2a: River Flooding

River flooding mainly happens when the river catchment (that is the area of land that feeds water into the river and the streams that flow into the main river) receives greater than usual amounts of water (for example through rainfall or melting of snow). The amount of runoff depends on the soil type, catchment steepness, drainage characteristics, agriculture and urbanisation as well as the saturation of the catchment. The extra water causes the level of the water in the river to rise above its banks or retaining structures.

Enquiry	Result	Contact
Is there a potential risk of river flooding within 250m of the property?	Yes	-

Section 2b: Coastal Flooding

Coastal flooding is the inundation of land areas along the coast caused by sea water rising above normal tidal conditions. Coastal flooding can arise from a combination of high tides, wind induced tidal surge, storm surge created by low pressure and wave action.

Enquiry	Result	Contact
Is there a potential risk of coastal flooding within 250m of the property?	No	-

Section 2c: Surface Water Flooding

Surface water flooding results from rainfall running over ground before entering a watercourse or sewer. It is usually associated with high intensity rainfall events (typically greater than 30mm per hour) but can also occur with lower intensity rainfall or melting snow where the ground is already saturated, frozen, developed (for example in an urban setting) or otherwise has low permeability.

Enquiry	Result	Contact
Is there a potential risk of surface water flooding within 250m of the property?	Yes	-

Next Steps

In order to gain more detailed information on the type and likelihood of your property being impacted by a flood event, and the potential impact on insurance, we recommend that you purchase our Landmark Flood Report.

If you would like more information please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email **helpdesk@homecheck.co.uk.**

Flood data provided by JBA Risk Management Limited. © Copyright JBA Risk Management Limited 2008-2023

Section 3: Radon Findings

The information within this section tells you whether the property is located in a radon affected area. Radon is a radioactive gas which occurs naturally in rocks and soils. You cannot see, hear, feel or taste it. Exposure to particularly high levels of radon may increase the risk of developing lung cancer, and is therefore something you need to be aware of or should consider.

Enquiry	Result	Contact
Is the property in a radon affected area?	The property is in a radon affected area, as between 5 and 10% of homes are above the action level	2
What level of radon protection measures for new dwellings or extensions to existing ones is required for the property?	Basic radon protective measures are necessary in the construction of new dwellings or extensions	2

Next Steps

The level of radon concentration can only be established by having the building tested. Action should be taken if the indoor radon level is measured and found to be above 200 becquerel's per cubic meter. If you would like any further information we recommend you contact Public Health England whose details can be found in the 'Useful Contacts' section of this report.

Further Action

Airtech Environmental Systems can advise on radon testing kits, which cost £39.36 including VAT and can run from 7 days to 3 months. They also have a team of surveyors on hand to provide recommendations and advice for any properties above the target level of 100 becquerel's per cubic meter or action level of 200 becquerel's per cubic meter. Airtech Environmental Systems can provide a report, recommendations and a quotation for any recommended works. For more detailed information please call their free-phone number 0800 378017.

Section 4: Ground Stability Findings

This section provides summary information on factors that could affect the ground stability of the property. It considers both manmade factors (e.g. mining activity) and natural hazards (e.g. geological stability).

Section 4a: Man-Made Factors

Enquiry	Result	Contact
Is the property within 25m of a Coal Mining Affected Area?	No	-

Section 4b: Natural Factors

Enquiry	Result	Contact
What is the potential for natural ground instability in the area within 50m of the property?	Moderate	-
Comment: The British Geological Survey has assessed the area of search as having moderate potential for natural ground instability. This does not necessarily mean there is cause for concern in terms of the property's stability. Active subsidence will be dependent on local conditions, such as the proximity of trees or areas where trees have been removed, which require an inspection of the site to identify the nature of the ground on which the property is built. A house buyers survey is advised to look for signs of property damage that may indicate poor natural ground conditions.		

Next Steps

This section has highlighted that ground stability is an area of concern, meaning that your property may be affected by subsidence or land-heave. If you would like any further information in respect of the above findings we recommend that you purchase our Homecheck Mining and Subsidence Report. Please contact your Search Provider or our Customer Services Team on **0844 844 9966** or email **helpdesk@homecheck.co.uk.**

Coombes Moor

Presteigne, LD8 2HY

Section 5: Other Influential Factors

The following section provides information on a variety of factors which may have an influence on the property or surrounding area.

Section 5a: Environmental Constraints

	Result	
npacted by Environmental Constraints?	Yes	
Details	Distance	Contact
Total Area (m2): 182281.71	180m	3
	Details	npacted by Environmental Constraints? Yes Details Distance

Next Steps

If you would like any further information in respect of the above findings we recommend that you get in touch with those listed in the 'Useful Contacts' section of this report. Each contact reference shown in the above table relates to detailed contact information contained within the back of this report.

Coombes Moor

Coombes Moor Presteigne, LD8 2HY

Useful Contacts

Contact 1 - Environment Agency - National Customer Contact Centre (NCCC) PO Box 544 Tel: 03708 506 506 enquiries@environment-agency.gov.uk Templeborough Rotherham s60 1BY enquiries@environment-agency.gov.uk Contact 2 - Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards

Chilton Didcot Oxfordshire OX11 0RQ	Tel: 01235 822622 Fax: 01235 833891	radon@phe.gov.uk www.ukradon.org
Contact 3 - Natural England		
County Hall Spetchley Road Worcester WR5 2NP	Tel: 0300 060 3900	enquiries@naturalengland.org.uk www.naturalengland.org.uk
Contact 4 - Herefordshire Cour	ncil	
Brockington 35 Hafod Road Hereford Herefordshire HR1 1SH	Tel: 01432 260000	www.herefordshire.gov.uk
Landmark Information Group I	Limited	
Legal and Financial Imperium Reading Berkshire RG2 0TD	Tel: 0844 844 9966 Fax: 0844 844 9980	helpdesk@homecheck.co.uk www.landmarkinfo.co.uk

The Landmark website contains links to many of our data suppliers which may prove useful.

Please note that the Environment Agency/Natural Resources Wales/SEPA have a charging policy in place for enquiries.

Landmark works in association with:



Report Version: HCP v1.0.4.5

Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY Report Reference 311649245_1_1 ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 18 of 21

Useful Information

The following explanatory notes may be of assistance to users of the Homecheck Professional report. Practitioners are reminded that full guidance notes are contained in the Practitioners Guide.

Professional Opinion

A Professional Opinion in relation to Part 2A of the Environmental Protection Act 1990 is provided by Argyll Environmental Consultants. In many cases the report will be PASSED without referral. However, in some cases, entries that may be of concern are revealed by the search, in which case the report is REFERRED free of charge for more detailed consideration, although this will not include a physical site inspection. After such referral the report may be PASSED or suggestions made of some FURTHER ACTION that could be taken, in the form of questions to ask of the appropriate authorities. When responses to these questions are received it is the responsibility of the client and their professional advisors to decide if they are happy to proceed.

Flood Risk

A limited flood risk screening exercise is included in this report designed to satisfy basic flood risk screening due diligence including consideration of river, coastal and surface water flooding. Where a potential flood risk is "Identified" you may wish to consider commissioning a more detailed flood risk screening report. When there is "None Identified" this does not indicate that there is not risk of flooding at the property, but that the risk of flooding from the sources screened (river, coastal and surface water) within the vicinity of the property is such that the risk may not be considered significant.

Location Map

The Ordnance Survey location map may show features which are not necessarily otherwise included in this report. You are advised to supplement the information contained in the report with the descriptive text shown on the map.

Positional Accuracy

We locate data in a variety of ways according to information provided to us and subsequent in-house research. If data is provided as a point on the ground, we provide a "positional accuracy" which tells you how confident we are of the actual location.

Section 1b: Landfill and Waste

At present no complete national data set exists for landfill site boundaries, therefore, a point grid reference, provided by the data supplier, is used for some landfill sites. In certain cases the point grid references supplied provide only an approximate position, and can vary from the site entrance to the centre of the site. Where the exact position of the site is unclear for Registered Landfill data, Landmark construct either a 100 metre or 250 metre "buffer" around the point to warn of the possible presence of landfill. The size of this "buffer" relates to the positional accuracy that can be attributed to the site. The "buffer" is shown on the map as a red hatched area. For further information regarding landfill sites identified in the report, please contact the relevant environment agency or authority referenced in the Useful Contacts section.

The BGS holds records of over 3,000 landfill sites that accepted waste prior to the Control of Pollution Act (COPA) 1974. These were not subject to any strict regulation or monitoring.

Permitted Waste Sites and Environmental Permitting Regulations - Waste cover current or recently current consents issued for landfill sites, waste transfer, treatment or disposal sites by the Environment Agency/Natural Resources Wales, under Section 64 of the Environmental Protection Act 1990 (Part 2) and prescribed by regulation 10 of SI No. 1056 of the Waste Management Licensing Regulations 1994.

Section 1c: Potentially Contaminative Activities

Identified discharge consents could be for storm water discharges, soakaways or septic tanks.

If a radioactive substance licence has been identified the consent band will be given under enquiries and replies. Consents fall into one of four bands: Band 1 and 2 Nuclear licensed sites authorised by the Nuclear Installations Inspectorate e.g. nuclear power stations Band 3 Site registered/authorised to accumulate and dispose of radioactive materials, only non-nuclear operations are carried out on site e.g. hospitals Band 4 Sites registered to keep and use radioactive material e.g. laboratories, universities, commercial premises using appliances such as monitoring equipment, alarm systems, tritium lighting etc.

Data supplied for Explosive Sites, Control of Major Accident Hazards Sites (COMAH) and Notification of Installations Handling Hazardous Substances (NIHHS) contains public sector information published by the Health and Safety Executive and licensed under the Open Government Licence.

Section 1e: Other Potential Contaminative Land Uses

This section relates to categories of potentially contaminative land uses that have been identified by the analysis of selected Ordnance Survey historical mapping. The published date (range of dates) of the map (s) and the distance from the centre of search to the nearest point of the feature is given. Further details of the extent of the site or its activities are not available. Should you wish to examine the Ordnance Survey maps these are normally available for public inspection at the local archive or local major library. Alternatively, extracts of editions of Ordnance Survey maps are available on www.old-maps.co.uk

Potentially infilled land has been identified when a 'cavity' (a hole made by an extractive industry or natural occurrence e.g. pond) was indicated on a historic map but there was no evidence of its existence in the last available map for the area. No details of what may have been used to fill the cavity or exactly when or if it was filled are available from the mapping.

The point locations of historical tanks and energy facilities are identified from the text on Ordnance Survey 1:1250 and 1:2500 scale mapping published between 1943 and 1996, based upon a predetermined list of abbreviations, e.g. El Sub (Electricity Sub-station) and F Stn (Filling Station). The position of the point has been located at the centre of the identified text so that it would be within approximately 30 meters of the feature it was describing. The features themselves are related to energy and petroleum storage and cover the following: tanks, petrol storage, potential tanks (at depots etc.), electricity sub stations and related features, gas and gas monitoring related features, oil related features and miscellaneous power features. NB: It should be noted that the Ordnance Survey abbreviation for tank (tk) is the same as that for tracks. Therefore some of the captured text may relate to tracks and not tanks when the exact nature of the feature is not clear from the mapping.

Homecheck® Report

The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY Report Reference 311649245_1_1

©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 19 of 21

Section 2: Flood Findings

Sections 2a, b and c of the report provide data on modelled extents of river, coastal and surface water flooding generated by JBA Risk Management, a market leader in flood risk assessment commonly engaged by insurers to assess flood risk. The data has been modelled for several perils or return periods: 1 in 75, 1 in 200 or 1 in 1000 which relate to areas with a 1.3%, 0.5% and 0.1% annual probability of flooding in any one year respectively. Properties at risk of flooding during a 1 in 75 year event are typically considered to be at a high risk of flooding. The data has been generated to provide a UK wide screening tool and as a result may have inherent limitations. In addition, there may be areas of the country which are modelled to varying degrees of accuracy based on currently available topographical information.

Section 3: Radon Findings

Due to the nature of way the information is gathered, your property/site may have more than one probability of radon attributed to it. We report the worst case scenario on the property/site you have provided. This information is an estimate of the probability that a property /site in Great Britain is at or above the "Action Level" for radon (the level at which Public Health England recommends that radon levels should be reduced, those with an average of 200 Bq m-3 or more). This information satisfies CON29 Standard Enquiry of Local Authority; 3.13 Radon Gas: Location of the Property in a Radon Affected Area. Where the property/site is a new build, this information provides information on the level of protection required for new buildings under BR211 (Scivyer, 2007) Radon: Guidance on protective measures for new buildings.

Disclaimer: "Some of the responses contained in this section are based on data and information provided by the Natural Environment Research Council (NERC) or its component bodies the British Geological Survey (BGS). Your use of any information contained in this report which is derived from or based upon such data and information is at your own risk. Neither NERC, BGS nor Public Health England where applicable, gives any warranty, condition or representation as to the quality, accuracy or completeness of such information and all liability (including liability for negligence) arising from its use is excluded to the fullest extent permitted by law."

Section 5a: Environmental Constraints

The Local Nature Reserves national dataset is "indicative" not "definitive". Definitive information can only be provided by individual local authorities and you should refer directly to their information for all purposes that require the most up to date and complete dataset.

General

If after reading the details in this report regarding the sites identified, you still require further information, please contact the relevant environment agency or authority indicated in the Useful Contacts section quoting the corresponding reference given in the text of the report.

The contacts in the Useful Contacts section may be able to provide further information relating to items identified in the report, however they are not in a position to advise how these might affect the value of a property. The findings of the report should be discussed with your professional advisor.

The Purpose and Scope of the Report

The report is designed to satisfy the concerns raised by the Law Society warning card and has been prepared to assist conveyancing professionals who may be advising clients when they sell or buy a property, obtain a mortgage, seek further mortgage advice, or commence any building works. It is designed to bring information to their attention and help them decide whether they need to seek any further specialist advice. As the report is so detailed, this information can cause concern, but professional advisors will see that further action is suggested on all issues that have been identified.

Limitations

This report has been published by Landmark Information Group Limited ("Landmark") and is supplied subject to our Terms and Conditions of Business, which can be found at <u>http://www.landmarkinfo.co.uk/Terms/Show/534</u>. It has been prepared on the understanding that it is to be used for an individual residential property transaction and should not be used or relied upon in a commercial property transaction. This report is neither a guarantee of the physical condition of the subject property nor a substitute for any physical investigation or inspection. The information in Homecheck Professional is derived from a number of statutory and non-statutory sources (see The Practitioner Guide for details). Whilst every effort is made to ensure the details in the report are correct, Landmark cannot guarantee the accuracy or completeness of such information or data, nor identify all the factors that may be relevant. If you are a private individual using this report Landmark recommends that you discuss its contents in full with your professional advisor. The methodology for risk assessment and the conclusions drawn therefrom are the responsibility of Argyll Environmental Consultants.

Insurance

Houses registered between 1st April 1999 and 31st December 2002 and covered by the NHBC Buildmark scheme probably have insurance against certain costs if contamination occurs within ten years of their construction. From 1st January 2003, NHBC will only provide this cover if building control has been carried out by NHBC Building Control Services Limited.

Landmark Standard Terms and Conditions

Full Terms and Conditions can be found on the following link: <u>http://www.landmarkinfo.co.uk/Terms/Show/534</u> If you experience difficulties accessing our Terms and Conditions, please copy and paste the link directly into your browser, you will then be able to access our Terms and Conditions from there. Should you still experience difficulties, please telephone our Customer Service Team on 0844 844 9966.

Copyright Statement

The data supplied for this Homecheck Professional report falls under the following copyrights: © Landmark Information Group and/or its Data Suppliers 2023; © Environment Agency and database right 2023; © Environment Agency & United Kingdom Research and Innovation 2023; ©Experian Ltd 2023; Produced in whole or in part under licence from, and based in whole or in part from copyright material of © Thomson Directories Limited; © The Coal Authority owns the copyright to this data and the coal mining information used to produce it; © Peter Brett Associates LLP 2023; © Ofcom copyright 2023; © Natural England copyright. Contains Ordnance Survey data © Crown copyright and database right 2023; Ordnance Survey © Crown copyright and/or Database Right. All rights reserved. Licence 100022432; © HS2 Ltd and licensed under the Open Government Licence; © Natural Resources Wales & United Kingdom Research and Innovation 2023; Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right.

Homecheck® Report The Bank Coombes Moor Coombes Moor Presteigne, LD8 2HY Report Reference 311649245_1_1 ©Copyright 2023, Landmark Information Group Ltd All rights reserved Date 22 May 2023 Page 21 of 21

Consumer Protection





Important Consumer Protection Information

This search has been produced by Landmark Information Group Ltd, Imperium, Imperial Way, Reading, Berkshire, RG2 0TD

Tel: 0844 844 9966

Fax: 0844 844 9980

Email: helpdesk@landmark.co.uk

Landmark adheres to the Conveyancing Information Executive (CIE) standards.

The Standards:

- Conveyancing Information Executive Members shall act in a professional and honest manner at all times in line with the Conveyancing Information Executive Standards and carry out the delivery of the Search with integrity and due care and skill.
- Compliance with the Conveyancing Information Executive Standards will be a condition within the Conveyancing Information Executive Member's Terms and Conditions.
- Conveyancing Information Executive Members will promote the benefits of and deliver the Search to the agreed standards and in the best interests of the customer and associated parties.
- The standards can be seen here: <u>http://www.conveyinfoexec.com</u>

Complaints

If you have a query or complaint about your search, you should raise it directly with the search firm, and if appropriate ask for any complaint to be considered under their formal internal complaints procedure. If you remain dissatisfied with the firm's final response, after your complaint has been formally considered, or if the firm has exceeded the response timescales, you may refer your complaint for consideration under The Property Ombudsman scheme (TPOs). The Ombudsman can award up to £5,000 to you if the Ombudsman finds that you have suffered actual financial loss and/or aggravation, distress or inconvenience as a result of your search provider failing to keep to the Standards.

Please note that all queries or complaints regarding your search should be directed to your search provider in the first instance, not to TPO.

TPOs Contact Details:

The Property Ombudsman scheme Milford House 43-55 Milford Street Salisbury Wiltshire SP1 2BP

Tel: 01722 333306 Fax: 01722 332296 Website: <u>www.tpos.co.uk</u> Email: <u>admin@tpos.co.uk</u>

Consumer Protection





Landmark Complaints Procedure

If you want to make a complaint to Landmark, we will:

- Acknowledge it within 5 working days of receipt
- Normally deal with it fully and provide a final response, in writing, within 20 working days of receipt
- Keep you informed by letter, telephone or e-mail, as you prefer, if we need more time
- Provide a final response, in writing, at the latest within 40 working days of receipt
- Liaise, at your request, with anyone acting formally on your behalf

Complaints should be sent to:

Customer Relationships Manager Landmark Information Imperium Imperial Way Reading RG2 0TD

Tel: 0844 844 9966 Email: <u>helpdesk@landmark.co.uk</u> Fax: 0844 844 9980

If you are not satisfied with our final response, or if we exceed the response timescales, you may refer the complaint to The Property Ombudsman scheme (TPOs): Tel: 01722 333306 Email: <u>admin@tpos.co.uk</u>

We will co-operate fully with the Ombudsman during an investigation and comply with his final decision.